

पत्र क्र. 1137 । एच.डी. सी/ सागर दिनांक 07/07/21

प्रति

प्राचार्य

महर्षि विद्या मेदर स्कूल


लैहदरा नाका भोपाल मार्ग सागर (म.प्र.)

विषय: Bholaiyedy Saty Certificate
चालने का पत्र

— x —

उपरोक्त विषयों के अन्तर्गत
लेवें हैं कि आपके पत्र दि. 28/6/2021 द्वारा
महर्षि विद्या मेदर स्कूल का भवन सुरक्षा
प्रमाण पत्र मांगार था। मैं भवन का
निरीक्षण उपरोक्त दिने गये। मालिक के
अवगत भवन का सुरक्षा प्रमाण पत्र
मिथी। निरुपय-में आपकी ओर प्रस्तुत
है।

अतः पत्र: Bholaiyedy Saty
Certificate प्राप्त (1) क (1)


अनुविभागीय अधिकारी
लो. वि. वि. उप संभाग क्र. 1, सागर

PROFORMA FOR THE SAFETY OF SCHOOL BUILDING

PART- 1

(To be filled by the Head of School/ Institute)

1. Name of the School : Maharishi Vidya Mandir
2. Location : Lehdana Vell. P.O. Sagara
Bhopal Road Sagara
3. Plot Area : 240451 Sq.ft
4. Plinth Area : 244578 Sq.ft
5. Number of Storey's : G+1.
6. Year of Construction of Building : 1995.
7. **If the building has been constructed under the supervision Of the qualified Engineer, the following details may be given**
 - a) Name of the Engineer with qualification : Sh. Vinay Rajwade C Diploma
Civil Engg
 - b) Address of Engineer : House No. 76 Vijay Nagar Jabalpur
C.P.
 - c) Set of Structural drawings used in the construction, if available : Not available
 - d) Name & address of Architect with qualification : Sh. S.P. Atkar Engineer
S.P. Builders Pt. 44 Madan Mohan
Chouk Nagour Road Jabalpur
8. **Whether the building has been constructed for the purpose**
 - a) School : YES/ NO
 - b) Residential Purpose and converted for use as a School : YES/ NO
9. **Materials used for roofs**
 - a) R.C.C. Slabs/R.B.C. Slabs : YES/ NO
 - b) R.S. Joist & Battons : YES/ NO
 - c) Wooden joists & Battons : YES/ NO
10. **Materials used for walls**
 - a) Mud Mortar : YES/ NO
 - b) Cement Mortar : YES/ NO
 - c) Lime Mortar : YES/ NO
11. **Flooring**
 - a) Conglomerate : YES/ NO
 - b) Terrazo : YES/ NO
 - c) Brick Paving. : YES/ NO
12. **A detailed drawing indicating dimensions of the rooms Alongwith size and location of doors and windows (Attached)**

Prfced 1/7/2021
Sub E

Sub Divisional Officer
P.W.D. Sub Division No. 1 Sagar

ATUL VERMA
Principal
Maharishi Vidya Mandir
Sr. Sec. Public School, Sagar (M.P.)
Signature with Stamp of the seal

PART-II

(To be filled by the S.D.E.)

- a) I have visited the above mentioned school on dated 11/7/2021..... And have visually inspected it from all angles of safety and find it fit for normal use as School buildings.
- b) In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
- c) In case the building is affected by food, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.
- d) This building can be safety occupied for normal use upto (indicate upto which it can be used)

01/07/2026.....


Sub Divisional Officer
PSW.D. Sub-Division No. 1 Sagar
Sub-Divisional Engineer,

~~Pravin~~ 11/7/2021
sebley
P.W.D. CB/2/
Sagar